ATE		003/12/23 : CIA-RDP66B00664F	2 3	10
2138Z Ø6 MAR	₹ 64 °E	ta propa and the control of the cont		12
o : DIRECTOR		gyptissääsi, väi sistä yli vaimikkiis olisi vaiminesi vaimaateliki yteen <b>aanastalais</b> kastataista tai taista tai	6	15
ROM :	25X1A	4 4	The second of th	. Maria de la composition della composition dell
ACTION: OPS	1-1-		ROUTINE	
HFO :		<u>*</u>	Emergraph e eye accepts constitution management a	The second secon
TOR: 2353Z	6 MAR 64			IN 664125X

25X1A

SUBJECT: FILM EVALUATION MISSION SØ74E.

- 1. CAMERA B 10 WAS USED IN MISSION S074E FLOWN ON 1 MARCH 1964;
  PROCESSING WAS ACCOMPLISHED BY 25X1A
  - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS FAIR TO GOOD DUE TO ATMOSPHERIC CONDITIONS.
- B. 9R SIDE: THE FILM WAS RECEIVED AT THE PROCESSING SITE WITH INTERMITTENT MINOR CREASES AND SMALL TEARS ALONG BOTH EDGES POSSIBLY DUE TO THE FILM MISTRACKING. THIS DAMAGE IS LESS THAN THAT REPORTED ON MISSION 0064E. NUMEROUS SHORT PLUS DENSITY STREAKS OF VARIOUS LENGTHS AND LOCATED RANDOMLY ACROSS THE FORMAT ARE NOTICEABLE IN LOW DENSITY FRAMES. TWO ALTERNATING PLUS DENSITY STREAKS, PARALLEL TO THE FILM EDGES, ARE PRESENT 3.3" FROM THE OUTBOARD EDGE AND 3.25" FROM THE INBOARD EDGE OF THE FILM THROUGHOUT. A ROW OF MINUS DENSITY DOTS, SPACED 1.55" APART, ARE PRESENT 1.6" FROM THE AND PARALLEL TO THE OUTBOARD EDGE OF THE FILM THROUGHOUT. A WAVERING PLUS DENSITY STREAK, APPROXIMATELY 6.25" LONG, IS PRESENT IN FRAMES 1290

SECRET Enclosed from and downspreading a declaratification

Approved For Release 2003/12/23: CIA-RDP66B00664R000400020044-7
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. Copy N

Approved For Release 2003/12/23 : CIA-RDP66B00664R039400020044-7

25X1A

71935 (IN 66412) SECRET PAGE TWO

AND 1323. NANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 2394 AND 2728.

- C. 9L SIDE: A WAVERING MINUS DENSITY STREAK OCCURS ALONG THE INBOARD EDGE OF THE FILM ON FRAME 801 TO THE MANUFACTURER'S SPLICE IN FRAME 805. TWO ROWS OF MINUS DENSITY DOTS, SPACED 1.55" APART. OCCUR 0.1" AND 3.2" FROM AND PARALLEL TO THE INBOARD EDGE OF THE FILM THROUGHOUT. MANUFACTURER'S SPLICES ARE PRESENT IN FRAMES 1983 AND 3152.
  - D. BOTH SIDES: FRAMES ARE TITLED 0000 THROUGH 3258.
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS ENCOUNTERED DURING THIS MISSION.
  - 3. POSITIVE:
- A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY CLOUDS AND HAZE.
  - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 25 PERCENT OF THE MISSION.

END OF MESSAGE

SECRET